



Pre-Authorization

Pre-Authorization number	PREAUTH69737 (PA03962103)	Reference no.	78918	Status	Approved
--------------------------	---------------------------	---------------	-------	--------	----------

Servicing Dealer	1194	Name	Basden's American RV	Address	600 E Baseline Rd Evansville, IN 47725	VIN	4YDTSGK29T7101268	Retail sold on
------------------	------	------	----------------------	---------	---	-----	-------------------	----------------

Root			Approved		Actual			
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	Base hours	Complaint/Cause/Correction
3302103A	Dinette Cushions - Repair	0	0.2	0.2		1	0.2	Complaint: STAIN ON COUCH CUSION Cause: Stain on couch Correction: Removed stain with mineral spirits and a rag.
2200902B	Roof Vents - 14"x 14" - All - Garnish	0	0.2	0.1		1	0.1	Complaint: INSIDE VENT SHROUD IS CRACKED IN BATHROOM Cause: replace vent shroud. Correction: removed damaged vent shroud and took maesurements. traced out new shroud and cut to fit. installed new shroud on vent.
2300102A	Entrance Door - Hinged - Repair	0	0.2	0.2		1	0.2	Complaint: ENTRY DOOR HARD TO LATCH Cause: Latch on the entry door is out to far. Correction: Moved the latch over towards the frame with a hammer.
Pre-authorization number: PREAUTH69737				0.5				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.