



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH739 30 (PA03966140	Reference no.78939	Status	Approved
--------------------------	---------------------------------	--------------------	--------	----------

Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDTSGM27S7103029	Retail sold on 1/31/2026
------------------------------	----------------------------------	--	------------------------------	---------------------------------

Root		Approved Actual				Base		
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
5101803A	Cord, 120V Shoreline - Hard 0		0.3	0.3		1	0.3	Complaint: SHORE CORD PLUG IN IS NOT
	Wired - Repair							TURNED THE RIGHT WAY
								Cause: Shore cord receptacle turned
								Correction: Took shore cord receptacle off
								and took the back off and turn the inside
								about 90 degrees and put the screws back
								in and sealed it back up. Tested it when
								done and it works properly

Pre-Authorization number: PREAUTH73930 0.3

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.