



KEYSTONE

Pre-Authorization

Pre- Authorization number: PREAUTH746 Reference no.79044 Status: Approved
 24
 {PA03966840 }

Serviceing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd VIN 4YDTCGM24TV500613 Retail sold on 12/6/2025
 Evansville, IN 47725

Root	Operation Description	Sublet	Approved Actual			Qty	Base hours	Complaint/Cause/Correction
			Sub Hours	Hours	hours			
4149014A	Refrigerator - 12 Volt	0	0.5	0.5		1	0.5	Complaint: CUSTOMER STATES THE FRIDGE IS OFF CENTERED AND LEANING FORWARD Cause: Fridge leaning Correction: Took a picture of the bottom of the fridge leaning out and the top leaning inwards. Discussed options with ben about resolving this problem. Found an extra piece of stile. Then cut it to size and screwed it below the fridge to keep the fridge feet inside the cabinet. Took pictures of the process.
5101706B	Cord, 120V Shoreline - Detachable - Replace	0	0.1	0.1		1	0.1	Complaint: CHECK SHORE POWER CORD. CUSTOMER STATES THE LOCKING RING IS BROKEN Cause: Locking ring broke Correction: Took pictures and put in parts request for a new locking ring for the shore cord.
Pre-Authorization number: PREAUTH74624							0.6	

For paper claims only use one pre-authorization number per warranty claim form.
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.