



Pre-Authorization

Pre-Authorization number: PREAUTH79688 (PA03971676) Status: Approved

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd Evansville, IN 47725 VIN 4YDTSGK23T7101251 Retail sold on 2/28/2026

Root		Approved		Actual	Qty	Base	Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours		hours	
5101906B	Light, Clearance & Taillight - Replace	0	0.2	0.2	1	0.2	Complaint: REAR TAILLIGHT NOT WORKING CORRECTLY Cause: Replace right rear tail light Correction: On inspection of this unit found that three of the led lights were not working. So i put a parts request in for a new. And it came in so i removed the old light znd replaced it with a new one and it sealed it with clear silicone. I tested it and it works properly. good to go now.
5102406B	Light, 12V Interior - Replace	0	0.2	0.2	1	0.2	Complaint: REPLACE INTERIOR LIGHT Cause: Light flickering in Living/Dinning area Correction: Replaced flickering shorting out light.
Pre-Authorization number: PREAUTH79688				0.4			

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.