

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13017

Date In: 17 OCT 25 Author: DLUCAS
Promised Date: 25 DEC 25 Stock No: 11259
: Year: 2025
Customer Name: 122926 - MCDONOUGH, MI Manufacturer: FOREST RIVER
Address: 1148 S. BUTTERCUP CT. Brand: PUMA DESTINATION
: FRIENDSHIP, WI Model: 402LFT
Postal/Zip: 53934 Miles/Hrs: 0
Phone#(res): 262-939-5796 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: YMIKEJ@YAHOO.COM Tag#: DB: 11/13
Purchased Date: 21 JUN 25 :
Delivery Date: 28 JUN 25 :
InService Date: :
Serial#: 4X4TPUS2XSP104319 :

Job # Description JOB INFORMATION Type Bill To

SC SERVICE CALL TO CUSTOMERS PROPERTY: 1003 MOOR CRT E 122926 MCDON
1 COMPLAINT: CUSTOMER STATES WATER HEATER IS STILL W 1021 FORES
THROWING CODES AND WHEN GOING TO LIGHT
IT IT LIGHTS FOR A SECOND AND THEN GOES
OUT AND SHUTS OFF AND DOESNT TRY TO
RESTART (PROBLEM IS RANDOM WORKS
SOMETIMES DOESNT WORK OTHERS SEEMS LIKE
FLAME SENSE IS BAD)**TAPPED ON THE
SOLENOIDS ON LEFT SIDE WITH SCREW DRIVER
AND HAS BEEN WORKING SINCE** **HAS BEEN
IN CONTACT WITH LIPPERT**
CAUSE: when trying the water heater multiple
times it didn't come on it was throwing
a e2 code i banged on gas valve and then
ran water it came on customers needs a
new water heater
CORRECTION: customer needs a new water heater REQ:
2 HOURS OF LABOR
2 COMPLAINT: Customer states pinholes in fabric of W 1021 FORES
shade at front on unit on left side of
couch
CAUSE: pinholes in fabric of shade need new
shade
CORRECTION: ...order shade REQUEST .40 HOURS OF
LABOR
3 COMPLAINT: CUSTOMER STATES PINHOLES IN FRONT W 1021 FORES
MOTORIZED SHADE BEHIND COUCH
CAUSE: Pinholes in fabric of shade, also shade

Continued on page 2

Work Order : 13017

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                keeps wanting to retract and drop down
CORRECTION: REQUEST .40 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  1  WARR      MANUFACTURER WARRANTY  JS  W-1021  0.50  140.00  70.00
  2  WARR      MANUFACTURER WARRANTY           W-1021  0.00  140.00   0.00
  3  WARR      MANUFACTURER WARRANTY           W-1021  0.00  140.00   0.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
  SC  SC      SERVICE CALL           E-122926  15.00  3.75  56.25

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
E  122926      0.00   0.00   0.00   56.25  3.11  59.36
W  1021        0.00  70.00   0.00   0.00   0.00  70.00

Totals      0.00  70.00   0.00  56.25  3.11  129.36

```

&k2S
&k0S