



Warranty Claim Form

Date: 7/31/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3220NDD04915
Transcend 255FK
Retail Purchase Date: null
Work Started: 5/22/2024
Work Completed: 5/22/2024

Claim Status: Paid
Dealer Work Order #: 10519
Unit Offline Date: 4/13/2022

Claim #: 821970
Labor: \$23.00
Parts: \$1.15
Shipping: \$0.00
Total: \$24.15

Notes: Shop supplies were credited at 5% of the approved labor for this job line (up to a max of \$25 per claim). 7/29 DW

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Operation Line # 1

Flat Rate Code: 590027 Range Hood Vent - Reseal

Fault Code: Damaged/Maintenance

Problem: Water leak in unit. Water found standing in unit after rain by salesman.

Hours: .2

Cause: Water leak found by sales staff on new lot for a transcend unit in kitchen area. Leak was from the vent hood exhaust for range hood. There was very little silicone around the vent, not enough to prevent leaks with heavy rains were had.

Amount: 23.00

Remedy: Cleaned and siliconed exhaust vent on the exterior of unit to prevent water getting in to the interior of unit.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.15