

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11078

Date In:	29 AUG 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	10604
:	:	Year:	2023
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	FLAGSTAFF CLASSIC TT
:	WISCONSIN RAPIDS, WI	Model:	832BWS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4X4TFLN28P1902563	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  THE TONGUE JACK ON THE UNIT IS NOT          W      1021    FORES
          OPERATING CORRECTLY- WILL NOT OPERATE AT
          ALL-
          CAUSE:      Front jack electronics are moisture
                      damaged, control pad deteriorated from
                      sun exposure. Needs replacement. Lippert
                      Smart Jack.
          CORRECTION: REQUESTING 1.50 OF LABOR
2      COMPLAINT:  LIGHT ABOVE DINETE IS BUSTED. ATTACHED      W      1021    FORES
          PIC. KARENA NOTICED.
          CAUSE:      Light above dinette has been rusting and
                      corroded. Moisture leaking into roof
                      area from broken solar connection at
                      rooftop. See pictures. Looks like
                      solar connector was fastened to roof
                      over a piece of debris causing an edge
                      to crack, over time the damage spread
                      allowing in moisture. Need to remove
                      and replace 12v puck light and solar
                      connection on roofline, 2x tube's white
                      dicor. (2hrs to remove and replace all
                      components, reseal and test)
          CORRECTION: R&R solar input connector and dining
                      puck light. REQUESTING 2 HOURS OF LABOR
*****
```

Continued on page 2

Work Order : 11078

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      82200671      LIGHT INTERIOR 4 1/2 LED W-1021      1      3.24      3.24
2      822020945      SOLAR ROOF TOP ELECTRICA W-1021      1      33.58      33.58
2      677917000333 Dicor 501LSW-1 EPDM Self W-1021      2      9.59      19.18
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
1 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.26      115.00      29.90
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00      115.00      0.00
1 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.24      115.00      27.60
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.17      115.00      19.55
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.26      115.00      29.90
2 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.07      115.00      8.05
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      56.00      115.00      0.00      0.00      0.00      171.00

      Totals      56.00      115.00      0.00      0.00      0.00      171.00
*****
```

&k2S
&k0S