

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2311342
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4FCRE26SS234418
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 020 / 020
 ITEM # CRF29RL
 DEALER RO # 12039
 CLAIM START DATE 05/27/2025
 CLAIM END DATE 07/28/2025

Labor rate: \$140.00

OWNER INFORMATION

THOMAS ZAGER
 8320 GROVE AVE
 Wisconsin Rapids, WI 54494
 USA

Retail Date of Purchase 05/12/2025 WARRANTY EXPIRATION DATE 05/12/2026

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 40-106-01-12-001225 Tail Light Assembly Bulb - Electrical/12 Volt Exterior/Replace/Exterior Lighting
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-05-27 09:57:14 :: Complaint: On the day of the showthru-
 the customer got home and realized that 3 of the diodes in the rear taillight are burnt out. Cause: Burnt out bulbs
 Correction: Replace taillight.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$42.00

Notes
 AUTHORIZED

Part

Line# 1	Item #	Description
	F100263840	EXTERIOR LIGHT, LED, RED OVAL TAIL LIGHT W/ LICENSE PLATE HOLDER & REFLECTOR - DS START VIN 227887
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$11.12
	Appr Qty 1.00	Appr Dlr Price \$11.12
		Part tag Sub Freight \$38.62
		Appr Freight \$38.62

Notes

Labor

Line# 2 Operation Code Operational Description
 30-100-01-00-001038 Cabinet Door Strut - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-05-27 09:58:52 :: Complaint: The arm that holds the
 pantry door from opening too far broke. Cause: Pantry arm became separated from wall. Correction: R&R pantry
 arm. Additional Note : greeneway@dealer-advisors.com, 2025-05-27 09:59:33 :: No correct code for this job.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$42.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$42.00

Notes
 CHANGED TO CORRECT CODE

Part

Line# 1	Item #	Description
	20X51854A	STRUT, COMPARTMENT/CABINET DOOR, GAS SHOCK, 20", 40 LB, ALSO USED ON MURPHY PANTRY [ED4]
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$5.85
		Part tag Sub Freight \$38.62

