



Warranty Claim Form

Date: 11/13/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3124T3353872
Reflection 260RD
Retail Purchase Date: 7/28/2025
Work Started: 10/10/2025
Work Completed: 10/10/2025

Claim Status: Paid
Dealer Work Order #: 12247C
Unit Offline Date: 6/12/2025

Claim #: 944777
Labor: \$28.00
Parts: \$0.00
Shipping: \$0.00
Total: \$28.00

Notes: JPH 10-27-25

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

JAMES JOHNSON
2525 S MEADOWVIEW LANE
APPLETON, Wisconsin 54915
United States
9205854083

Operation Line # 1

Flat Rate Code: 550032 Sealing - Attachments

Fault Code: Damaged/Maintenance

Problem: Roof has a few bubbles in dicor.

Hours: .2

Cause: Gaps in the dicor from the manufacturer.

Amount: 28.00

Remedy: Cleaned 2 small bubbles and sealed with leftover dicor after popping the bubbles.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: