



# Warranty Claim Form

Date: 1/15/2026

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FS3823RAA17955  
Solitude 3503GK  
Retail Purchase Date: 9/6/2024  
Work Started: 9/8/2025  
Work Completed: 9/8/2025

Claim Status: Paid  
Dealer Work Order #: 12397  
Unit Offline Date: 1/30/2024

Claim #: 938227  
Labor: \$210.00  
Parts: \$135.10  
Shipping: \$14.40  
Total: \$375.09

Notes: JPH 9-27-25 LINE 2 LCI has approved new range since repair did not fix the issue. JPH 7-31-25 Case 6079915 VIN 573FS3823RAA17955 LCI will approve up to 1.0 for labor. This is pre-auth for the R&R of the FOLLOWING: OVEN CONTROL-THERMOSTAT VALVE-2022120252 : C-FGR24D3A1A-11 PILOT FLAME-2021124185 : C-FSRI22LA-SS-PFlame Case #6079915 regarding 882563 As a courtesy to the tech I will approve an additional .5 hours labor.

### Dealer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Customer Information

ROSE BALSIGER  
W5743 S PARTRIDGE DR  
NEW LISBON, Wisconsin 53950  
United States  
608-547-9512

### Operation Line # 1

*Flat Rate Code:* 720103 Range/Oven - R & R Range/Oven *Fault Code:* Component Failure Assembly

*Problem:* Customer states oven turns on, gets to temp and turns off.

*Hours:* 1.5

*Cause:* Tested oven, set at 350 and the over burner comes on, reaching temp and shutting off. You physically have to shut the oven off and turn it back on to re-light.

*Amount:* 210.00

*Remedy:* R&R oven

*Sublet Repairs:*  
\$0.00

*Manufacturer #:* 1

*Model #:* 1

*Serial #:* 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
721539 RANGE OVEN CONTROL THERMOSTAT VALVE ONLY ( C-FGR24D3A1A-11 )	RANGE OVEN CONTROL THERMOSTAT VALVE ONLY ( C-FGR24D3A1A-11 )		1	1	135.10
720521 RANGE OVEN PILOT FLAME F/ FSRI22LA-SS (FURRIION C-FSRI22LA-SS-PFLAME)	RANGE OVEN PILOT FLAME F/ FSRI22LA-SS (FURRIION C-FSRI22LA-SS-PFLAME)		1	1	0.00

**Operation Line # 2**

*Flat Rate Code:* 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified  
Fee

*Problem:* Invoice 1468075

*Hours:* 0

*Cause:* Invoice 1468075

*Amount:* 0.00

*Remedy:* Invoice 1468075

*Sublet Repairs:* \$15.59

*Manufacturer #:*

*Model #:*

*Serial #:*