

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12462

Date In: 28 JUL 25 Author: MGRAY
Promised Date: 06 AUG 25 Stock No:
: Year: 2024
Customer Name: 3060 - SCHAUB, THOMAS Manufacturer: GRAND DESIGN
Address: Brand: IMAGINE XLS
: EAGLE RIVER, WI Model: 22MLE
Postal/Zip: Miles/Hrs:
Phone#(res): 715-479-9220 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TE2621R3439537 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - BATHROOM SINK IS W 1020 GRAND
LEAKING FROM THE HOT WATER SIDE
CAUSE: The faucet is leaking from the head. The
faucet will need replacement.
CORRECTION: ... REQUEST .60 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 2 - DRAWER IN KITCHEN W 1020 GRAND
REAR BOTTOM, DRAWER WILL NOT STAY IN
PLACE.
CAUSE: The drawer glide fell apart. I replaced
it
CORRECTION: Done. REQUEST .40 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 3 - WHEN NOT CONNECTED W 1020 GRAND
TO SHOREPOWER, SLIDES WILL NOT WORK.
CAUSE: NPF. I turned the battery disconnect
off, ran the slide in and out and
everything is working. I checked the
voltage at the battery before and after
being plugged in and the voltage is
good.
CORRECTION: Done.
WARR COMPLAINT: WARRANTY REPAIR 4 - refer doors are not W 1020 GRAND
remaining open.when storing the unit and
leaving the doors open to prevent mold
freezer door is not latching in that.
CAUSE: The freezer door latch won't hook into
the plastic block that keeps the doors
open when the unit is stored. The fridge
door will latch to the block. I tried

Continued on page 2

Work Order : 12462

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                           flipping the block around and it didn't
                                           change anything. We have to see if the
                                           manufacturer wants us to try a different
                                           block, door latch or leave it because
                                           it's still preventing the doors from
                                           closing.
WARR    CORRECTION: ... NEED MANUFACTURER ADVISEMENT
COMPLAINT: WARRANTY REPAIR 5 - MATRESS HAS A DIP IN W    1020    GRAND
          CAUSE: Faulty mattress. We have to see what
          the manufacturer wants to do
CEU     CORRECTION: ... REQUEST .30 HOURS OF LABOR
COMPLAINT: CLEAN EXTERIOR- USED                           E    3060    SCHAU
          CAUSE: 1001 CUSTOMER REQUESTED. I washed the
          exterior including the awning and slide
          out.
          CORRECTION: Done.

```

```

*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
WARR0 822057300 BEARING DRAWER GLD 18`` W-1020 2 7.06 14.12

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.50 140.00 70.00
ARR02 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.50 140.00 70.00
ARR03 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.50 140.00 70.00
ARR04 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.50 140.00 70.00
ARR05 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.50 140.00 70.00
CEU CE CLEAN EXTERIOR JGK E-3060 0.87 140.00 121.80
ARR01 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.00 140.00 0.00
ARR02 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.00 140.00 0.00
ARR03 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.00 140.00 0.00
ARR04 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.00 140.00 0.00
ARR05 Z992 MISC LABOUR CODE (WARR JGK W-1020 0.00 140.00 0.00
CEU CE CLEAN EXTERIOR JGK E-3060 0.00 140.00 0.00
CEU CE CLEAN EXTERIOR JGK E-3060 0.12 140.00 16.80
CEU CE CLEAN EXTERIOR JGK E-3060 0.11 140.00 15.40
ARR01 W150 FAUCET, R & R W-1020 0.00 140.00 0.00

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR04 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 11.55 11.55

```

Continued on page 3

Work Order : 12462

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	3060	0.00	154.00	0.00	0.00	8.48	162.48
W	1020	14.12	350.00	0.00	11.55	0.00	375.67
	Totals	14.12	504.00	0.00	11.55	8.48	538.15

&k2S
&k0S