



# Warranty Claim Form

Date: 11/4/2025

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573TM2722T1223250  
Momentum 21G  
Retail Purchase Date: null  
Work Started: 10/10/2025  
Work Completed: 10/10/2025

Claim Status: Paid  
Dealer Work Order #: 12561C  
Unit Offline Date: 8/6/2025

Claim #: 940640  
Labor: \$1190.00  
Parts: \$0.00  
Shipping: \$0.00  
Total: \$1190.00

Notes: AB 10/17 \*Please hold all parts for a minimum of 30 days after the claim is paid\*

### Dealer Information

### Customer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Operation Line # 1

*Flat Rate Code:* 410001 Wiring Short/Ground - Diagnostic *Fault Code:* Improper Installation/Build Time

*Problem:* When the tech went to install the new power awning on the rear of the unit, found that there is no power supply wire run to the rear of the unit.

*Hours:* 8.5

*Cause:* When checking the power supply to the awning switch, found that the switch only had 8 volts.

*Amount:* 1190.00

*Remedy:* We will need to run a new wire from the converter to the switch threw the underbelly. Will need to run 18', we have all the materials here to do the job.

*Sublet Repairs:*  
\$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*