

Claim CLAIM29257 (C3872602)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Changed		Date of Purchase
								Labor rate	warranty rate	
CLAIM29257 (C3872602)	12761	9/24/2025	9/24/2025	4YDTHPU23R9330277	PA03922603	1612	Greenway Inc 8220 State Hwy 13 S Wisconsin Rapids, WI 54494	140.00	0.00	WARR 5/20/2025

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3104916B	Bed - Panel	0.2	0.2	28	0	1	0.2	Approved
<p>Complaint *THIS IS NOT A WALL* The front side of the king bed is loose but it just needs to be stapled/nailed down.</p> <p>Cause Panel on the bottom of the bed popped loose.</p> <p>Correction Reattached the panel with crown nails *NO BED REPAIR CODE* Approve accordingly as the flat rate of 0.1 hours is not enough time.</p> <p>KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.</p>									

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	2201515D	Awning & Gutter Rails	0.3	0.3	42	0	1	0.1	Approved
<p>Complaint The awning leaks above the door where it is attached to the camper.</p> <p>Cause Awning leaks above the entrance door.</p> <p>Correction Romed eterna bond tape and sealed with non sag dicor.</p> <p>KRV – Labor time adjusted allowing for proper repair procedure to be performed.</p>									

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	70.00	Approved labor & subLet	70.00
Submitted freight	0.00	Approved freight	0.00
Total Submitted	<u>70.00</u>	Total approved	<u>70.00</u>