



Warranty Claim Form

Date: 11/4/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE3426N6639508

Imagine 2910BH

Retail Purchase Date: 6/27/2022

Work Started: 10/9/2025

Work Completed: 10/9/2025

Claim Status: Paid

Dealer Work Order #: 12888

Unit Offline Date: 2/25/2022

Claim #: 939690

Labor: \$112.00

Parts: \$24.01

Shipping: \$0.71

Total: \$139.49

Notes: Sg 10/15/25 *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Jesse Hoffmann
8355 State Highway 80
Marshfield, Wisconsin 54449-9673
United States
715-305-5740

Operation Line # 1

Flat Rate Code: 910045 Recalls/Field Campaign - Quick Disconnect *Fault Code:* Recall
(supersedes 910029)

Problem: 24V-861 Quick disconnect recall.

Hours: .6

Cause: Quick disconnect recall.

Amount: 84.00

Remedy: Replaced the quick disconnect and tested it. Had to scrub it to try to make out the engravings.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
220061 QUICK DISCONNECT X 1/4 BRASS SHUT OFF W/PLUG AF	QUICK DISCONNECT X 1/4 BRASS SHUT OFF W/PLUG AF		1	1	24.01

Operation Line # 2

Flat Rate Code: 920014 - Customer Satisfaction Campaign - Imagine *Fault Code:* TSB
2910BH Web Crack Inspection

Problem: Recall on I-Beam cracking.

Hours: .2

Cause: Inspected both sides and there is no visible cracking.

Amount: 28.00

Remedy: Inspection only.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 950003 Misc. Charges - Handling Fee

Fault Code: No Problem Identified

Problem: Invoice 1428095 (only claiming 1/20 of handling fee as only 1 part was used)

Hours: 0

Cause: Invoice 1428095 (only claiming 1/20 of handling fee as only 1 part was used)

Amount: 0.00

Remedy: Invoice 1428095 (only claiming 1/20 of handling fee as only 1 part was used)

Sublet Repairs: \$2.77

Manufacturer #:

Model #:

Serial #: