



# Warranty Claim Form

Date: 12/5/2025

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FS372XSAA20617  
Solitude 3203GK  
Retail Purchase Date: 2/5/2025  
Work Started: 11/24/2025  
Work Completed: 11/24/2025

Claim Status: Paid  
Dealer Work Order #: 13134  
Unit Offline Date: 12/18/2024

Claim #: 949880  
Labor: \$70.00  
Parts: \$7.98  
Shipping: \$0.00  
Total: \$77.98

Notes: JPH 11-20-25

### Dealer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Customer Information

LINDA LINDGREN  
1362 DUCK CREEK CT  
FRIENDSHIP, Wisconsin 53934  
United States  
7153230338

### Operation Line # 1

*Flat Rate Code:* 330002 Lines - Fresh Water Line Repair      *Fault Code:* Improper Installation/Build

*Problem:* Where the bathroom slide goes out there is a hose that is getting kinked. When slide is all the way out, the bathroom sink does not have water going to it.      *Hours:* .5

*Cause:* Water line gets kinked when bedroom slide is out under vanity.      *Amount:* 70.00

*Remedy:* Will need to re-route lines to prevent kinks. Possibly add a spring to assist in which direction to pull lines. Removed the front fascia board to access the water line area, added a retainer spring to redirect the lines from getting kinked in the future when the slide is put in or out.      *Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 use only	Miscellaneous Part for claim use only		1	1	7.98