

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 13232

Date In: 19 FEB 26	Author: KOTT
Promised Date: 25 DEC 26	Stock No: 11468
:	Year: 2026
Customer Name: 1021 - FOREST RIVER	Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE	Brand: PUMA DESTINATION
: CHICAGO, IL	Model: 403LFT
Postal/Zip: 60673-1218	Miles/Hrs: 0
Phone#(res): 219-534-3167	Exterior Color:
Phone#(bus): 219-534-3167	Unit Type: TT-TRAVEL TRAILER
Cell Phone:	License#:
Email: NONE	Tag#:
Purchased Date:	:
Delivery Date:	:
InService Date:	:
Serial#: 4X4TPUS27TP106899	:

 Job # Description JOB INFORMATION Type Bill To

 1 COMPLAINT: REPAIR ALL SLIDE OUTS FROM MANUFACTURER W 1021 FORES
 NOT COMPLETELY SEALING THE SIDE SLIDE
 WALLS BEHIND THE FASCIA BOARD-
 CAUSE: Add eterna bond tape to back of fascia
 on all slides to cover exposed wood.
 CORRECTION: Put eterna bond tape on slides after
 removing facia for proper install.

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
1	891991000533	ETERNABOND WHITE		W-1021	4	1.86	7.44

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
1	WARR	MANUFACTURER WARRANTY	TD		W-1021	0.00	140.00	0.00
1	WARR	MANUFACTURER WARRANTY	TD		W-1021	0.50	140.00	70.00
1	WARR	MANUFACTURER WARRANTY	TD		W-1021	0.00	140.00	0.00

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	7.44	70.00	0.00	0.00	0.00	77.44
	Totals	7.44	70.00	0.00	0.00	0.00	77.44

Continued on page 2

Work Order : 13232

&k2S
&k0S