



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$129.61

RO# : 40193 Tag# : TE760398

Check-in: Fri Feb 27, 2026 | 8:25 AM
Ready for Pickup: Fri Mar 13, 2026 | 9:17 AM
Promise Time: Wed Mar 4, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVU20 TE760398
1 Mi In / 1 Mi Out
In Service Date:
01/01/2017
Stock #: KS26-29

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES THERES BROKEN CORNER MOULDING IN CLOSET	Warranty Pay	\$129.61
----	---------------	---	--------------	----------

Job added by KEVIN GOODIEL on Fri Feb 27, 2026 | 8:25 AM

1. Overtightened screws on uneven surface. .50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.28	0.3	0.3	\$49.50	\$9.30

1. Removed the damaged corner molding and trimmed the batten strip and corner trim down so the molding would fit better and more evenly, then fastened the new molding in place.

Parts

Parts Total Sale Amount \$24.60

Parts Total Cost Amount \$18.92

Name	Quantity	Unit Price	Sale Price	Cost Price
756339 - Cover - Recessed Triangle Corner - 25 3/4" x 32 1/2" - ABS - Black	1	\$24.60	\$24.60	\$18.92

Fees \$55.51

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$55.51	\$0.00

Total Labor Sale
\$49.50

Total Labor Cost
\$9.30

Total Parts Sale
\$24.60

Total Parts Cost
\$18.92





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$129.61

RO# : 40193 Tag# : TE760398

Check-in: Fri Feb 27, 2026 | 8:25 AM

Ready for Pickup: Fri Mar 13, 2026 | 9:17 AM

Promise Time: Wed Mar 4, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVU20 TE760398

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$49.50	\$9.30
	Parts	\$24.60	\$18.92
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$55.51	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$129.61	\$28.22

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Fri Mar 13, 2026	8:43 AM	9:00 AM	0.28 hrs	W	lafavet	0.3 hrs

Tag: Regular Hour

Reason: -

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40193	LINK RV	\$129.61
57200	40193	LINK RV	-\$49.50
67200	40193	LINK RV	\$9.30
14400	lafavet	LINK RV	-\$9.30
54200	40193	LINK RV	-\$24.60
64000	40193	LINK RV	\$18.92





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$129.61

RO# : 40193 Tag# : TE760398

Check-in: Fri Feb 27, 2026 | 8:25 AM
Ready for Pickup: Fri Mar 13, 2026 | 9:17 AM
Promise Time: Wed Mar 4, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVU20 TE760398

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
14000	40193	LINK RV	-\$18.92
76710	40193	LINK RV	-\$55.51

