



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913
1 Mi In
Stock #: FR26-20

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES FABRIC ABOVE ODS FRONT TIRE IS RIPPED.	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Debris from tire

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.13	0	0	\$0.00	\$0.00

1. Holes in fabric above tire. Recommend new fabric

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES THE ROOF NEEDS TO BE SEALED IN SPOTS	Warranty Pay	\$49.50
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Missed sealant





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.23	0.3	0.3	\$49.50	\$7.20

1. Applied white quad around both extrusions on rear.

Total Labor Sale
\$49.50

Total Labor Cost
\$7.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C.	MISCELLANEOUS	DEALER STATES BLIND ABOVE STOVE IS MISSING PLASTIC WAND.	Warranty Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Missing stick to turn the blinds. Recommend ordering stick.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.04	0	0	\$0.00	\$0.00

1. Took photo of missing stick

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

D.	MISCELLANEOUS	DEALER STATES BLIND IN SLIDEOUT, CLOSEST TO REAR DOES NOT STAY UP.	Warranty Pay	\$66.00
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM

Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM

Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

1. Loose string.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00

Labor Cost: \$9.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.32	0.4	0.4	\$66.00	\$9.60

1. Unscrewed string. Moved knot up. Tested. Clipped excess string.

Total Labor Sale
\$66.00

Total Labor Cost
\$9.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

E. MISCELLANEOUS	DEALER STATES DECORATIVE FASCIAS TRIM ON SLIDEOUT IS PEELING.	Warranty Pay	\$49.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Horizontal top fascia trim has nick and peeling laminent. "Weather protectant fascia board wrap" for lack of a proper term is protruding from the top of trim. Recommend new fascia trim and cut and hide fascia wrap.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.24	0.3	0.3	\$49.50	\$7.20

Total Labor Sale
\$49.50

Total Labor Cost
\$7.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

F. MISCELLANEOUS	DEALER STATES SHOWER DOESN'T WORK ON HOT OR COLD, POSSIBLY CLOGGED.	Warranty Pay	\$66.00
-------------------------	--	---------------------	----------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 9:58 AM

1. Construction debris

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00

Labor Cost: \$9.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.22	0.4	0.4	\$66.00	\$9.60

1. Removed shower head. Hit with pressurized hose from both ends. Reattached. Works as it should. There was a noticeable amount of debris in waste tank that was apparent after draining.

Total Labor Sale
\$66.00

Total Labor Cost
\$9.60

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

G. MISCELLANEOUS	DEALER STATES THE PLASTIC COVER FOR 30 AMP PLUG IN IS BROKEN	Internal Pay	\$36.00
------------------	--	--------------	---------

Tags: [Add-on](#)

Job added by KEVIN GOODIEL on Tue Mar 10, 2026 | 1:30 PM

1. ????

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$36.00

Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.15	0.3	0.3	\$36.00	\$7.20

1. Opened 30 amp plug to provide power. Cover came off. Receptacle is broken at hinge. Recommend new receptacle.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Total Labor Sale
\$36.00

Total Labor Cost
\$7.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

	Category	Sale	Cost
	Labor	\$267.00	\$40.80
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$267.00	\$40.80

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Mar 10, 2026	1:04 PM	1:12 PM	0.13 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Mar 10, 2026	1:12 PM	1:26 PM	0.23 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Tue Mar 10, 2026	1:26 PM	1:27 PM	0.01 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 10, 2026	1:27 PM	1:31 PM	0.07 hrs	W	matthewl	0.4 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$267.00

RO# : 40250 Tag# : TB941913

Check-in: Tue Mar 10, 2026 | 9:58 AM
Ready for Pickup: Wed Mar 11, 2026 | 8:58 AM
Promise Time: Sun Mar 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER
5ZT2AVPB1TB941913

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	Tue Mar 10, 2026	1:31 PM	1:33 PM	0.03 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
D	MISC	Tue Mar 10, 2026	1:33 PM	1:48 PM	0.25 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
E	MISC	Tue Mar 10, 2026	1:48 PM	2:02 PM	0.24 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Tue Mar 10, 2026	2:02 PM	2:15 PM	0.22 hrs	W	matthewl	0.4 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Tue Mar 10, 2026	2:16 PM	2:25 PM	0.15 hrs	I	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40250	LINK RV	\$231.00
57200	40250	LINK RV	-\$231.00
67200	40250	LINK RV	\$33.60
14400	matthewl	LINK RV	-\$33.60

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
14300	FR26-20	LINK RV	\$36.00
57300	40250	LINK RV	-\$36.00
67300	40250	LINK RV	\$7.20
14400	matthewl	LINK RV	-\$7.20

