



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72946
Promised Date:
07 FEB 26

72946

WO #: 72946

Customer Name: 61082 - WOOD,
TIMOTHY ALAN

Completed Date: 27 FEB 26

Invoice#:

Author: J.LINDAMAN

Stock Desc: 9533 2026 GRAND STAR
3444

Serial#: 950277

Chassis#: 4UZA9FC8TCWM6896

Miles/Hrs: 1495

Tag#:

Purchased Date: 12 JAN 26

Warranty Date: 20 FEB 26

Date In: 20 FEB 26

Time In:

Job #01 - Internal

COMPLAINT: SFD - MOTORHOME

CAUSE: Sfd

CORRECTION: Completed
See added jobs

Labor

Job #	Description	Total
01	SFD MOTORHOME	N/C

Parts

Part #	Description	Qty	Price	Total
9688	DIESEL EXHAUST FLUID	2.00	N/C	N/C
18926	CUSTOM SPRAY PAINT - GLOSS SMOKE GREY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #01: 0.00

Job #1 - Warranty

COMPLAINT: Rear air conditioner makes rubbing noise when on

CAUSE: Fan rubbing against housing

CORRECTION: Adjusted and tested. Completed .5 hr

Labor

Job #	Description	Total
1	REAR AIR CONDITIONER MAKES RUBBING NOISE	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: SWAP SOFA EST # 4950

CAUSE: Removed old sofa. Installed trim, sealed holes and trim.

Customer #: 61082
WOOD, TIMOTHY ALAN

61082

CORRECTION: Removal and trim / seal retrofit completed
Estimated Amount: 4,694.64

Labor		Total
Job #	Description	N/C
2	SWAP SOFA	

Subtotal for Job #2: 0.00

Job #3 - Internal
WET

Subtotal for Job #3: 0.00

Job #04 - Internal
COMPLAINT: DEWINTERIZE

CAUSE: Dewinterize

CORRECTION: Completed

Labor		Total
Job #	Description	N/C
04	DEWINTERIZE	

Subtotal for Job #04: 0.00

Job #4 - Warranty

COMPLAINT: Oasis module fault. Zone fault

CAUSE: Air in fuel line to oasis. Zone module set to summer loop.

CORRECTION: Purged air from system. Set zone module to normal use. Tested. Completed
.5 hr

Labor		Total
Job #	Description	N/C
4	OASIS MODULE FAULT	

Subtotal for Job #4: 0.00

Job #5 - Internal

ADD BATTERY PROTECTANT

Labor		Total
Job #	Description	N/C
5	ADD BATTERY PROTECT	

Subtotal for Job #5: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

W/O: 72946
Promised Date: 27 FEB 26

72946

Customer #: 61082
WOOD, TIMOTHY ALAN

61082

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 27 Feb 2026

Customer Signature : _____

Customer Work Order

W/O: 72946
Promised Date: 27 FEB 26

72946

Customer #: 61082
WOOD, TIMOTHY ALAN

61082