



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72471
 Promised Date:
 02 FEB 26



WO #: 72471
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 30 JAN 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9618 2026 R-POD
 UN-MAPPED 26ML
 Serial#: 035467
 Chassis#: 4X4TUMB29TB035467
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 09 OCT 25
 Time In:

Job #1 - Internal
 CHECK IN NEW UNIT

Subtotal for Job #1: 0.00

Job #PDI1 - Internal
 COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: PDI NEEDED.

CORRECTION: PDI COMPLETED.

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	10.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal
 COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize unit.

CORRECTION: Unit has been winterized.

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #WIN-STD: 0.00

W/O: 72471
Promised Date: 03 FEB 26

Job #2 - Warranty

COMPLAINT: Trim above bedroom is coming off

CAUSE: Paneling too low causing insert trim to detach from track.

CORRECTION: Must resecure paneling and adjust track depth to allow for insert trim attachment. Need .30 hrs

Labor

Job #	Description	Total
2	PANELING	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Panel near bed frame is coming off

CAUSE: Fasteners detaching

CORRECTION: Need to remove detached fasteners and resecure paneling. Perform trim work. Requesting .30 hrs

Labor

Job #	Description	Total
3	PANELING	N/C

Subtotal for Job #3: 0.00

Customer Work Order



Customer #: 1000
MYERS "RV" CENTER,
INC.,

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 30 Jan 2026

Customer Signature : _____

