



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72775
 Promised Date:
 30 JAN 26



WO #: 72775 (Appointment Date: 17 DEC 2025 - Time: 09:15am)
 Customer Name: 60837 - SANTOS SOSA, MIGUEL GABRIEL
 Completed Date: 30 JAN 26
 Invoice#: Author: ADVISOR
 Stock Desc: 9611 2026 R-POD RP-200
 Serial#: 4X4TRPV20TB035307
 Chassis#: 4X4TRPV20TB035307 Date In: 17 DEC 25
 Miles/Hrs: Time In:
 Tag#: 7039
 Purchased Date: 17 OCT 25
 Warranty Date: 17 OCT 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES ENTRY DOOR IS NOT LATCHING - CUST. REMOVED STRIKER IT IS LAYING ON ENTRY FLOOR

CAUSE: No issue found

CORRECTION: Customer removed striker plate, reinstalled striker plate and tested function. Door is latching as designed. No corrective action taken at this time. Job completed

Labor

Job #	Description	Total
1	ENTRY DOOR ADJUST	38.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 38.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES CANNOT GET FRIDGE OUT OF OFFGRID MODE. FRIDGE IS OFF NOW BUT ONCE TURNED ON IT AUTOMATICALLY GOES TO OFFGRID

CAUSE: Freezer fan failure

CORRECTION: I spoke with Cathy at Lippert, she informed me that number two flashing on the eyebrow is a fan failure and said I need to order a new fan and disassemble the shelves and rear panel of the freezer removal of fan blade removal of fan motor and reassemble and test function. Part number 2024017875 is the part number for that fan. 1.0 hours needed for fan replacement.

Lippert case # 6449925.

Job completed, tested, working as designed.

Labor

Job #	Description	Total
2	REFRIGERATOR	209.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 60837
 SANTOS SOSA, MIGUEL
 GABRIEL



F100729742 REFRIGERATOR PART:FREEZER FAN 1.00 372.61 372.61
 & COIL COVER ASSEMBLY / FOR
 FURRIION

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	16.26	16.26

Subtotal for Job #2: 597.87

Parts Total: 372.61
 Labour Total: 247.00
 Sublet Total: 0.00
 Extras Total: 16.26
WORK ORDER TOTAL: 635.87

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 30 Jan 2026

W/O: 72775
 Promised Date: 29 JAN 26



Customer #: 60837
 SANTOS SOSA, MIGUEL
 GABRIEL

