

Nexus Dealer

Phone: Phone:

b.parrott@myersrv.com;Rhianna.s@myersrv.com

Date of Purchase:

Year: 2026 Make: Ghost Model: 38DS

VIN: 1HTEUMML1TS217297

AUTHORIZATION #: 17154

Nexus RV Serial Number: 18780
 Work/Repair Order: 72932
 Service In Date: 02/17/2026
 Service End Date:
 Mileage: 1,679.00
 Bill Ref #: 17154
 Bill Ref # Date:

Date: 02/19/2026 Created By: Christy

Estimate Prepared For Customer:

Status: Authorization Approved

Estimate Prepared For Service Location: 98001

Myers RV Center
 12024 Central Ave SE

 Albuquerque NM, 87123

Item Code	Description	Complaint	Cause	Correction	Rate	Qty	Amt	Nexus Hrs	Nexus Amt
1 3420R	TRIM FLAT TRIM RESECURE	Trim is loose at slide on insude passenger side above kitchen	Fasteners failed	Pull fasteners and reinstall trim.	195.00	0.50	97.50	0.50	97.50
2 3028X	OVERHD CABINET ASSEMBLY TOUCH-UP (PER CABINET)	Screw coming through panel under cabinet on drivers side abocve dinette, two locations	Screw over penetration	Repair ceiling and reinstall trim after screw removal and replacement	195.00	1.00	195.00	1.00	195.00
							Requested	Authorized	
							\$292.50	\$292.50	

Comments:

Nexus Subtotal: \$292.50
 Sales Tax: \$0.00
 Total: \$292.50