



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72648
Promised Date:
10 NOV 25



WO #: 72648 (Appointment Date: 10 NOV 2025)

Customer Name: 60904 - GIFFORD,
DAVID

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 2024 SENECA XT
Serial#: 1UJNJCBP8RI1JT4051
Chassis#: 1FDFF6LT0PDA05733
Miles/Hrs: 8137
Tag#: 6886
Purchased Date:
Warranty Date:

Date In: 10 NOV 25
Time In:

Job #0 - Warranty

CLAIM# J01466370-001 AUTH'D FOR 1.0

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES RECALL RECEIVED - TSB#:25-015 - THE ORIENTATION TO BE
CHANGED FOR THE LP REGULATOR & COVER

CAUSE: TSB

CORRECTION: TSB instruct for inspection. Inspection showed regulator needs to be installed correctly and
parts needs to be ordered.
1.00HRS

Labor

Job #	Description	Total
1	LP REGULATOR RECALL	17.90

Parts

Part #	Description	Qty	Price	Total
25-015JM	KIT, LP REGULATOR ORIENTATION AND COVER (TSB 25-015JM)	1.00	27.22	27.22

Subtotal for Job #1: 45.12

Job #2 - Warranty

COMPLAINT: Transferred to RV*72648-1 on 03 DEC 25
Estimate amount was 0.00
CUSTOMER STATES TOUCH PANEL INSIDE INOPERATIVE

CAUSE: Component failure. Open on wire from screen to firefly G2 board

CORRECTION: Removed screen from mount connect directly to board. Turned screen on and used all
functions. Recommend replacement of wire from firefly board to location of touchscreen. Requesting five
hours to route new wire. Need to order orange network cable app approximately 20 feet long. After routing
of new wire controller has to be set to correct floor plan. All items need to be retested to ensure proper
operation of the board.

Labor

Job #	Description	Total
2	ELECTRICAL REPAIR	0.00

Customer #: 60904
GIFFORD, DAVID



Subtotal for Job #2: 0.00

Parts Total: 27.22
Labour Total: 17.90
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 45.12

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

****MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND****

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 07 Jan 2026

W/O: 72648
Promised Date: 10 NOV 25



Customer #: 60904
GIFFORD, DAVID

