

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2547392
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRRB0TB526225
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT255DS
PAULA MANUEL		DEALER RO #	72817
1316 MONTERREY RD NE		CLAIM START DATE	01/12/2026
Rio Rancho, NM 87144		CLAIM END DATE	02/25/2026
USA			
Retail Date of Purchase	08/23/2025	WARRANTY EXPIRATION DATE	08/23/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	70-157-01-00-001821	Refrigerator Door Gasket - Appliances/Refrigerator (Dometic)/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-12 10:14:43 :: Complaint: Customer states refer door seal is flat and does not seal properly Cause: Door seal came off and is damaged Correction: Recommend replacement of the refer door seal Additional Note : stephanie@dealer-advisors.com, 2026-01-13 09:01:41 :: Shipping address is 12024 Central Ave Se, Albuquerque, NM 87123

Model#	fcr11dcgta	Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#	10001883121022500057	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes

Forest River is currently reviewing your request with the Vendor. Please verify your shipping address, please acknowledge, placing the claim back on our side. We will update the line once we receive their response. Thank you. Dp
 Case 6490547 VIN 5ZT2TRRB0TB526225 As a resolution to this case, we are approving up to .50 for labor. This serves as prior authorization for the removal and replacement of the FRESHER DOOR 2024017853. This pre-authorization is for informational purposes only and will not result in Lippert automatically issuing the replacement. Lippert will defer to the RV Manufacturer for next steps regarding replacement and claims filing. This product is not required to be returned for testing. Note: Your coach information will need to satisfy the conditions for Warranty credit. Mobile service fees are not covered under the Lippert warranty for this product. VCB .50 to R&R the refer door seal. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1	Item #	Description				
	F100702280	FRESHER DOOR ASSY, REFRIGERATOR RHH FURRIION FCR11DCGTA 2024017853, 2024120714 (9A-SOP)				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$218.74	Sub Freight	\$59.10
	Appr Qty	1.00	Appr Dlr Price	\$218.74	Appr Freight	\$59.10

Notes

Submitted	Labor Amt	\$190.00	Approved	Labor Amt	\$95.00
	Parts & Freight	\$277.84		Parts & Freight	\$277.84
	Total	\$467.84		Total	\$372.84

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.