

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2539719
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TRPU11TB034739
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT185-80
		DEALER RO #	71844
		CLAIM START DATE	01/02/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-02 10:10:20 :: Complaint: Trim in numerous places is loose Cause: Trim in numerous places is loose, not secure Correction: Restapled all loose trim in unit			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-92-01-00-001154	Sink Cover - Interior/Interior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-02 10:12:22 :: Complaint: Sink cover handle is missing screw Cause: Screw pulled out of wall Correction: Installed new screw to hold handle in place Additional Note : stephanie@dealer-advisors.com, 2026-01-02 10:15:22 :: ****this was the closest labor code I could find for this repair, no code for just a repair. Sink cover was NOT replaced, just a screw added.****			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.05	Appr Labor Amt	\$9.50
	Notes			
	excessive time requested. Time reduced based on photos, description and flat rate.			
	authorization to resecure with 1 screw			

Labor

Line# 3	Operation Code	Operational Description		
	20-43-01-00-003921	Key(s) - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-16 08:55:06 :: Complaint: No keys to the compartment doors Cause: Only one key for entry door Correction: Only one key in packet, noted on DAF. Keys need to be ordered,			
Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00
	Notes			

Submitted	Labor Amt	\$38.00	Approved	Labor Amt	\$28.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$38.00		Total	\$28.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.