



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72190-1
 Promised Date:
 07 FEB 26



WO #: 72190-1

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 26 FEB 26

Invoice#:

Author: ADVISOR

Stock Desc: 9593 2026 R-POD RP-203

Serial#: 035176

Chassis#: 4X4TRPV20TB035176

Date In: 23 DEC 25

Miles/Hrs:

Time In:

Tag#:

Purchased Date: 31 JAN 26

Warranty Date: 24 JAN 26

Job #2 - Warranty

COMPLAINT: Panel behind right front closet loose

CAUSE: Panel came loose

CORRECTION: Restapled panel back in place

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	38.00
Subtotal for Job #2:		38.00

Job #3 - Warranty

COMPLAINT: Hole in ceiling near air conditioner cover

CAUSE: Hole in ceiling panel

CORRECTION: Found a hole in the ceiling panel not punched all the way through
 Used a putty file stick and filled the hole

Labor

Job #	Description	Total
3	CEILING NEAR AVC	19.00
Subtotal for Job #3:		19.00

Job #4 - Warranty

COMPLAINT: Latch for lower bunk needs to be adjusted not holding bunk in the up right position

CAUSE: Not enough of the latch bar in the plate to hold the bed up right

CORRECTION: Found the lower bunk in the upright position the latch was not holding the bed up.
 Added a pice of batten trim behind the plate. Latch now holds the bed upright and will not fall

Labor

Job #	Description	Total
4	BUNK LATCH	19.00

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #4: 19.00

Job #5 - Warranty

COMPLAINT: Drivers side front marker light not working needs to be replaced

CAUSE: Marker light not working

CORRECTION: Found during the PDI the drivers side marker light was not working

Will need to replace hold for parts

Job complete

Labor

Job #	Description	Total
5	MARKER LIGHT	19.00

Parts

Part #	Description	Qty	Price	Total
20X73000A	LIGHT, 3/4" BULLET LIGHT, COOL WHITE	1.00	1.81	1.81

Subtotal for Job #5: 20.81

Job #6 - Warranty

COMPLAINT: Cabinet door damaged will need to be replaced found during the pdi see attached photos

CAUSE: Damaged door on the top

CORRECTION: Found the cabinet door was damaged on the top will need to be replaced

14 x 48

Labor

Job #	Description	Total
6	MULTIPLE LABOR CODES	76.00

Parts

Part #	Description	Qty	Price	Total
F100568392	DOOR, CABINET 14" X 48" FLAT PANEL - BRIGHTON WHITE	1.00	39.43	39.43

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	54.30	54.30

Subtotal for Job #6: 169.73

Parts Total: 41.24
 Labour Total: 171.00
 Sublet Total: 0.00
 Extras Total: 54.30
WORK ORDER TOTAL: 266.54

W/O: 72190-1
Promised Date: 27 FEB 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 26 Feb 2026

Customer Signature : _____

Customer Work Order

W/O: 72190-1
Promised Date: 27 FEB 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

