



12024 Central Ave SE ★ Albuquerque NM 87123  
www.MYERSRV.com  
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72178-1  
Promised Date:  
ALFRED JOSEPH



WO #: 72178-1

Customer Name: 59351 - KOOREY,  
ALFRED JOSEPH

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9532 2025 BAY STAR 3014

Serial#: 142191

Chassis#: 1F66F5DN7S0A00739

Date In: 22 SEP 25

Miles/Hrs: 4632

Time In:

Tag#: 6721

Purchased Date: 23 MAY 25

Warranty Date: 23 MAY 25

**Job #3 - Warranty**

COMPLAINT: CUSTOMER STATES THE SEATBELT ON THE DRIVER SIDE BINDS

CAUSE: Binding in head unit

CORRECTION: Replace order

**Labor**

Job #	Description	Total
3	SEATBELT	N/C
<b>Subtotal for Job #3:</b>		<b>0.00</b>

**Job #15 - Warranty**

COMPLAINT: CUSTOMER STATES RADIO PRESS TO CALL BUTTON INOPERATIVE

CAUSE: Called Newmar. Spoke with Phil. Sent pics for clarification

CORRECTION: Waiting for Newmar

**Labor**

Job #	Description	Total
15	PRESS TO CALL	N/C
<b>Subtotal for Job #15:</b>		<b>0.00</b>

**Job #8 - Warranty**

COMPLAINT: CUSTOMER STATES BUNK RASING PROBLEM; REQUIRES INCREMENTAL OPERATION AND LIFTING ASSISTANCE

CAUSE: Motor failure. Motor brake failure

CORRECTION: Motor gets very warm to touch and intermittently releases bed causing it to drop. No binding in belt system found. Replace motor and relay box from motor

**Labor**

Job #	Description	Total
8	OVERHEAD BUNK	N/C

Customer #: 59351  
KOOREY, ALFRED JOSEPH



Subtotal for Job #8: 0.00

**Job #13 - Internal**

COMPLAINT: CUSTOMER STATES UNIT IS VERY NOISEY GOING DOWN THE ROAD

CAUSE: Loud noise from tires and front suspension.

CORRECTION: Sublet

**Labor**

Job #	Description	Total
13	TEST DRIVE	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS-1	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #13: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Dec 2025

Customer Signature : \_\_\_\_\_

W/O: 72178-1  
Promised Date: 15 AUG 25



Customer #: 59351  
KOOREY, ALFRED JOSEPH

