



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25283



WO #: 25283

Customer: 59072 - EXTREME AUTOMOTIVE,
KYKERS
Address: 1201 TUSCULUM BLVD
GREENEVILLE, TN
37745

Home Phone: 423-525-5147

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10911

Stock Desc: 2024 FW FOREST RIVER CEDAR

CREEK 391WOW

Model: 391WOW

Serial #: 4X4FCRR27RS233105

Chassis #:

Mileage:

Key #: 13200

Req'n #:

License #:

Trim:

Purchase Date: 28 DEC 24

Date In: 15 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 28 DEC 24

Job #1 - Warranty

COMPLAINT: KITCHEN SLIDE TOPPER MATERIAL IS NOT CORRECT AND BUNCHING UP

CAUSE: THE TUBE IS BOWED IN THE MIDDLE AND CAUSING THE MATERIAL TO NOT ROLL UP CORRECTLY.

CORRECTION: REMOVE AND REPLACE THE COMPLETE SLIDE TOPPER HARDWARE AND MATERIAL. THERE IS NOT TAG ON THIS SLIDE TOPPER.

LABOR 2.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: POWER CORD WILL NOT RETRACT AND ROLL UP

CAUSE: REEL IS NOT WORKING AND WILL NOT ROLL UP. IT WILL WORK FOR JUST A SECOND AND THEN NOTHING.

CORRECTION: REMOVE AND REPLACE THE POWER CORD REEL THEN TEST

LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

INSTALL COUNTER TOP FROM W/O 25169. THIS JOB WILL BE COMPLETED AND CLOSED UP ON THAT W/O 25169

Subtotal for Job #3: 0.00

Job #4 - External

INSTALL WASHER/DRYER COMBO
THEY ARE IN THE FRONT COMPARTMENT

Parts

Part #	Description	Qty	Price	Total
72-4921	BLK DRYER VENT	1.00	40.12	40.12
72-4892	SECURE FIT SPLENDIDE	1.00	12.16	12.16
79-1989	AIR DUCT 4" X 25	6.00	0.79	4.74

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



Subtotal for Job #4: 57.02**Job #5 - External**ADD SCREWS TO AWNING ARM THAT WAS REPLACED BY CP. ARM DOES NOT LAY FLUSH
AGAINST THE UNIT**Subtotal for Job #5: 0.00****Job #6 - External**PASSENGER SIDE FRONT CAP HAS DAMAGE
CORY STATED HE HAS ENOUGH PAINT TO REPAIR**Subtotal for Job #6: 0.00****Job #7 - External**

TOP OFF LP

Subtotal for Job #7: 0.00**Job #8 - External**

CUST NEEDS UNIT BACK IN 3 WEEKS FROM 4/15/2025

Subtotal for Job #8: 0.00

Parts Total: 57.02
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 5.56

WORK ORDER TOTAL: 62.58

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 23 Apr 2025

Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS