

#2.

Performed Water Test on Slide Room, Performed First with Slide Room in Retracted Position - no Leaks found, Extended Slide & Re Performed Test - no Leaks found, only Leak found in Slide was from Compartment Door (Exterior)
Please see write up for Line #7 Compartment Leak
Can However Verify Water Damage To Cabinets Tech Jo

Will Need $3\frac{1}{4}'' \times 4'' \times 35''$

$3\frac{1}{4}'' \times 4'' \times 18.5''$

$3\frac{1}{4}'' \times 2'' \times 35''$ (x2)

$3\frac{1}{4}'' \times 3.5'' \times 35''$

GF+ $1'' \times 1''$

$3\frac{1}{4}'' \times 4'' \times 13''$

Please
See Photos