



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25554



WO #: 25554 (Appointment Date: 03 JUN 2025 - Time: 01:00pm)

Customer: 74694 - RENNER, RANDY
 Address: 285 STONE DAM RD
 CHUCKEY, TN
 37641

Home Phone: (423) 620-3782

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10913
 Stock Desc: 2024 FW FOREST RIVER
 SANDPIPER 4003MB
 Model: 4003MB
 Serial #: 4X4FSAS28RJ046573
 Chassis #:
 Mileage:
 Key #: 8500
 Req'n #:
 License #:
 Trim:

Purchase Date: 02 NOV 24
 Date In: 03 JUN 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 14 JUN 25
 Warr. Date: 02 NOV 24

Job #1 - Warranty

COMPLAINT: BED SLIDE NOT RUNNING OUT

CAUSE: BED SLIDE CONTROLLER IS NOT PUTTING POWER OUT TO THE MOTOR SO THE SLIDE WILL WORK AS DESIGNED TO.

CORRECTION: REPLACE THE SLIDE OUT ROOM CONTROL
 LABOR 1.5

Labor

Job #	Description	Hours	Total
1	REPLACED SLIDE OUT CONTROL	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100464990	SLIDE OUT, CONTROL FOR IN-WALL CABLE	1.00	135.80	135.80

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	18.50	18.50

Subtotal for Job #1: 236.80

Job #2 - External

SC KINSER PARK ON THE RIVER FRONT

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

FILL LP TANKS

Subtotal for Job #3: 0.00

Job #4 - External

CUSTOMER MUST HAVE UNIT JUNE 14

Customer #: 74694
 RENNER, RANDY



Subtotal for Job #4: 0.00

W/O: 25554

Parts Total:	135.80
Labour Total:	82.50
Sublet Total:	0.00
Extras Total:	18.50
WORK ORDER TOTAL:	236.80

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Jun 2025

Customer Work Order



Customer #: 74694
RENNER, RANDY

