



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 2906 COUCH, RANDALL



Estimate: 2906

Customer: 85225 - COUCH, RANDALL
 Address: 1907 LAKEWOOD DR
 MORRISTOWN, TN
 37814

Home Phone: (423) 492-3710

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11063

Stock Desc: 2025 TT FOREST RIVER

ROCKWOOD SIGN 8339FK

Model: 8339FK

Serial #: 4X4TRLN25S1908109

Chassis #:

Mileage:

Key #: 6445

Req'n #:

License #:

Trim:

Purchase Date: 05 JUL 25

Date In: 20 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 05 JUL 25

Job #1 - Warranty

ESTIMATE TO REPAIR DAMAGE FROM SLIDE TOPPER

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

REMOVE AND REINSTALL FRONT AWNING HARDWARE

Labor

Code	Description	Hours	Rate	Total
Z990	REMOVE FRONT MAIN AWNING HARDWARE	1	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

SAND, CLEAN, MASK OFF, GLASS, PAINT, REFINISH, AND BLEND HOLE NEAR MAIN AWNING

Labor

Code	Description	Hours	Rate	Total
Z990	REPAIR GOUGE NEAR MAIN AWNING	3.50	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

REMOVE AND REINSTALL SLIDE SEALS ON TOP, FRONT AND REAR OF SLIDE

Labor

Code	Description	Hours	Rate	Total
Z990	REMOVE AND REINSTALL 2 DOUBLE SIDED SLIDE SEALS	3	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

SAND, CLEAN, MASK OFF, GLASS, RESAND, PAINT, REFINISH AND BLEND REAR SLIDE CORNER

Labor

Code	Description	Hours	Rate	Total
Z990	REPAIR REAR CORNER FIBERGLASS	4	N/C	N/C



Subtotal for Job #5: 0.00

Job #6 - Warranty

SAND, CLEAN, MASK OFF, GLASS, RESAND, PAINT, REFINISH AND BLEND FRONT CORNER OF SLIDE

Labor

Code	Description	Hours	Rate	Total
Z990	REPAIR FRONT CORNER FIBERGLASS	4	N/C	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

REPLACE UPPER EXTERIOR SLIDE FACIA

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE EXTERIOR SLIDE FASCIA	1	N/C	N/C

Subtotal for Job #7: 0.00

Job #8 - Warranty

REMOVE AND REINSTALL INTERIOR SLIDE FACIA AND BACKING BOARDS

Labor

Code	Description	Hours	Rate	Total
Z990	REMOVE AND REINSTALL FACIA AND BACKING BOARDS	2	N/C	N/C

Subtotal for Job #8: 0.00

Job #9 - Warranty

REMOVE AND REINSTALL INTERIOR METAL RAIL ON TOP OF ROOF AND UPPER SIDES

Labor

Code	Description	Hours	Rate	Total
Z990	REMOVE AND REINSTALL INTERIOR RAILS	0.60	N/C	N/C

Subtotal for Job #9: 0.00

Job #10 - Warranty

OVEREXTEND SLIDE REMOVE AND REINSTALL SIDE TRIM AND REPLACE ROOF MATERIAL

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE SLIDE ROOFING MATERIAL	2.50	N/C	N/C

Subtotal for Job #10: 0.00

Job #11 - Warranty

REMOVE AND REINSTALL SLIDE ROOM AWNING HARDWARE, ROLLER TUBE, AND RAIL

Labor

Code	Description	Hours	Rate	Total
Z990	REMOVE AND REINSTALL AWNING	2.50	N/C	N/C

Subtotal for Job #11: 0.00

Job #12 - Warranty

SAND, PREP, FILL, PAINT, AND BLEND HOLES THAT SLIDE TOPPER RIPPED THROUGH ON REAR OF SLIDE

Labor

Code	Description	Hours	Rate	Total
Z990	REPAIR HOLES ON REAR OF SLIDE	2	N/C	N/C



Subtotal for Job #12: 0.00

Job #13 - Warranty

SAND, PREP, FILL, RESAND, PAINT AND BLEND HOLES THAT SLIDE TOPPER RIPPED THROUGH ON FRONT OF SLIDE

Labor

Code	Description	Hours	Rate	Total
Z990	REPAIR HOLES FRONT OF SLIDE	2	N/C	N/C

Subtotal for Job #13: 0.00

Job #14 - Warranty

INSTALL SLIDE TOPPER IN NEW HOLES TO AVOID STRIPPED AREAS IN BACKER

Labor

Code	Description	Hours	Rate	Total
Z990	INSTALL SLIDE TOPPER	1	N/C	N/C

Subtotal for Job #14: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	0.00
Estimate Total:	0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 20 Aug 2025

