



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25889



WO #: 25889

Customer: 69757 - HERRON, JEREMY
 Address: 395 LOOKOUT RIDGE DR
 NICKELSVILLE, VA
 24271

Home Phone: (276) 479-1278

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11128

Stock Desc: 2026 TT KZ-RV CONNECT 313MK

Model: 313MK

Serial #: 4EZTL3326T4056880

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 23 JUL 25

Date In: 06 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 08 AUG 25

Warr. Date: 23 JUL 25

Job #1 - Warranty

COMPLAINT: NO ANTENNA RECEPTION ON EITHER TV

CAUSE: DUE TO FACTORY INSTALL TWO CABLE WIRES BEHIND THE MAIN TV WERE PINCHED CAUSING NO SIGNAL TO MAKE IT THROUGH, TECH ALSO FOUND A SPLITTER NOT ALLOWING SIGNAL THROUGH

CORRECTION: REMOVE AND REINSTALL MAIN TV, REMOVE AND REINSTALL ANTENNA BOOSTER, CUT AND REPAIR TWO COAX ENDS, REPLACE SPLITTER
 LABOR 1

Labor

Job #	Description	Hours	Total
1	REPLACED SPLITTER	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
24-0423	TV CABLE SPLITTER, 4 WAY SPLITTER	1.00	11.16	11.16

Subtotal for Job #1: 186.16

Parts Total: 11.16
 Labour Total: 175.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 186.16

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 08 Aug 2025

Customer #: 69757
 HERRON, JEREMY

