



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25891



WO #: 25891

Customer: 91575 - MASON, DENNIS
Address: 1774 LITTLE DRY RUN RD
BUTLER, TN
37640

Home Phone: 423-291-0137

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10836

Stock Desc: 2024 TT FOREST RIVER

ROCKWOOD ULTRA 2608BS

Model: 2608BS

Serial #: 4X4TRLB27RZ189705

Chassis #:

Mileage:

Key #: 5000

Req'n #:

License #:

Trim:

Purchase Date: 01 JUL 24

Date In: 06 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 26 AUG 25

Warr. Date: 01 JUL 24

Job #1 - Warranty

COMPLAINT: BATHROOM FAUCET LEAKING OUT THE SIDE AND SPRAYING WALL

CAUSE: FAUCET DEVELOPED A CRACK IN THE SIDE, PART DEFECT.

CORRECTION: REPLACE FAUCET

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED FAUCET	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100481342	FAUCET	1.00	28.41	28.41

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	18.64	18.64

Subtotal for Job #1: 129.55

Parts Total:	28.41
Labour Total:	82.50
Sublet Total:	0.00
Extras Total:	18.64
WORK ORDER TOTAL:	129.55

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Aug 2025

Customer #: 91575
MASON, DENNIS

