

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2471925
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4FVGR27T5403628
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 081 / 081A
 ITEM # VGF391T145-81
 DEALER RO # 26047
 CLAIM START DATE 10/18/2025
 CLAIM END DATE 10/22/2025

Labor rate: \$165.00

OWNER INFORMATION

JONI DANIEL
 1770 W ALLENS BRIDGE RD
 Greeneville, TN 37743
 USA

Retail Date of Purchase 07/23/2025 WARRANTY EXPIRATION DATE 07/23/2026

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 20-56-19-00-000600 Slide Out T-Molding, each - Exterior/Slide Out System-Seals, Exterior Room/
 Reseal/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-10-18 14:18:07 :: Complaint: Customer said they get a water leak through the slide that has the couch in it Cause: Water leaking from top rail of slide room Correction: Apply sealant just behind slide seal to correct the concern and no more water is leaking down

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$33.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$33.00

Notes

Part

Line# 1 Item # Description
 USERPART Proflex sealant CLR 10oz

Model #	Serial #	Part tag	
Sub Qty 1.00	Sub Dlr Price \$12.38	Sub Freight	\$0.00
Appr Qty 1.00	Appr Dlr Price \$12.38	Appr Freight	\$0.00

Notes

Labor

Line# 2 Operation Code Operational Description
 30-92-01-00-001164 Ceiling Fan Bracket, each - Interior/Interior Miscellaneous/Replace/No Tread
 Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-10-18 14:20:29 :: Complaint: Customer said the front AC is leaking water in Cause: Tech found front mounting bolts are loose, causing AC gasket to not compress properly Correction: Resecure front mounting bolts on AC Additional Note : ashlee@dealer-advisors.com, 2025-10-18 14:30:44 :: Could not find an air conditioning code, please advise

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$66.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$66.00

Notes
 thank you

Labor

Line# 3 Operation Code Operational Description
 30-91-01-00-002753 Theater Seat or Sofa - complete - Interior/Living Quarters, Sofa, Chair/Replace/
 No Tread Code

Complaint, Cause, Correction

