



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26223



WO #: 26223

Customer: 93256 - REDDIN, MICHAEL
Address: 203 MIKES AVE
GREENEVILLE, TN
37745

Home Phone:
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11053
Stock Desc: 2025 TT KZ-RV CONNECT 262RLK
Model: 262RLK
Serial #: 4EZTL2827S4097049
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 20 SEP 25
Date In: 18 OCT 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 20 SEP 25

Job #1 - Warranty

COMPLAINT: LEFT DINETTE DOOR HANDLE ON CABINET WILL NOT TIGHTEN. THE HANDLE IS LOOSE ON ONE END CUST STATED.

CAUSE: WHERE THE SCREW GOES IN ONE END OF THE HANDLE IS STRIPPED OUT.

CORRECTION: REPLACE CABINET HANDLE
LABOR .20

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

Customer #: 93256
REDDIN, MICHAEL



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 18 Oct 2025

