



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26292



WO #: 26292

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11232  
 Stock Desc: 2026 FW FOREST RIVER  
 SANDPIPER 3900HBLR  
 Model: 3900HBLR  
 Serial #: 4X4FSAR26TJ048805  
 Chassis #:  
 Mileage: 0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 30 OCT 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 28 JAN 26  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: LIVING ROOM SLIDE WILL NOT GO OUT  
 FOREST RIVER WAS CONTACTED ABOUT THIS DUE TO THE DAF COULD NOT BE COMPLETED  
 BECAUSE OF THE SLIDE NOT WORKING CORRECTLY.

CAUSE: SLIDE ROOM GEAR PACK IS JUMPING TRACK, GEAR PACK IS FAULTY

CORRECTION: REPLACE GEAR PACK ON SLIDE (2X2 TUBE)  
 ADJUST ROOM TO BE SQUARE AND ADJUST ROOM  
 LABOR 3.0

**Labor**

Job #	Description	Hours	Total
1	REPALCED GEAR PACK AND ADJUSTED SLIDE	3.00	495.00

**Parts**

Part #	Description	Qty	Price	Total
90M06297A	SLIDE OUT GEAR PACK 2X2	1.00	70.25	70.25

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	19.43	19.43

**Subtotal for Job #1: 584.68**

Parts Total: 70.25  
 Labour Total: 495.00  
 Sublet Total: 0.00  
 Extras Total: 19.43  
**WORK ORDER TOTAL: 584.68**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 28 Jan 2026

Customer Signature : \_\_\_\_\_

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,

