

Part Order - S5444282 (Open Order)

VIN	4X4FRSR23N0002620	Submitted	02/06/2026	Ship To	TRI AM RV CENTER OF EAST TN
Business Unit	RV	RO#		Address	1202 IDELL ROAD (I-81 EXIT 23)
Make	RIVERSTONE	PO#	17718		BULLS GAP, TN 37711
Location		Notes			USA
Model	RSF39RKFB				423-235-1167
				Ship To	
				Contact	
				Shipping	UPS Ground
				Method	

Parts

Part #	Qty	Unit	Unit Price	Disc. Amt.	Net Amount
50G02378A	1	ea	14.24	0.00	\$14.24
Description					
LP, HOSE, Quick Disconnect W/ Dust Plugs, Model 250M Plug, 60", 1/4 HP PAN N 1 AFTERMARKET					
F100784753	1	ea	19.54	0.00	\$19.54
Description					
8K TANDEM AXLE BRAKE LINE REPAIR KIT WITHOUT HOSE, RECALL 25V550/2025-438 KIT INCLUDES 2- 5/16"-16 x 1" Bolt, 4-5/16" Flat Washer, 2-5/16"-16 NYLOCK Nut, 2--3.50" I.D. P-Clamp, AND 8-21.7" LPC-51HDB, Zip Ties					

26629
SU
11254