



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26690



WO #: 26690 (Appointment Date: 06 FEB 2026 - Time: 01:30pm)

Customer: 93644 - BOWLING, FREDDIE
Address: 26 CANEY LEFT LITTLE FRK
PIKEVILLE, KY
41501

Home Phone: 606-794-1121

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #:
Stock Desc: 2025 FOREST RIVER SALEM
Model:
Serial #: 4X4FSBN26TV013136
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 06 FEB 26
Promise Date:
Promise Time:
Schedule Date:
Completed: 03 MAR 26
Warr. Date:

Job #1 - Warranty

DOP ON UNIT IS 11-2025

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: HEAT IS NOT COMING ON IN THE UNIT
FURNACE IS LIGHTING WILL NOT SENSE THE FLAME

CAUSE: FURNACE WILL NOT LIGHT, BYPASSED THERMOSTAT, STILL NOT RUNNING. REMOVED FURNACE AND BENCH TESTED. FURNACE FIRED UP DURING TESTING, VOLTAGE 14.3 LP 12 WC. NO VOLTAGE OUT OF BOARD TO LP VALVE WHEN REINSTALLED. BENCH TESTED AND FOUND NO VOLTAGE OUT OF BOARD TO LP VALVE. TESTED WITH TEST BOARD, RUNS AND LIGHTS PROPERLY. (jcs)

CORRECTION: REPLACE BOARD AND TEST
LABOR AND DIAG 1.5

Labor

Job #	Description	Hours	Total
2	REPLACED BOARD	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
90M37474A	FURNACE, IGNITION CONTROL MODULE, 2023 ,VENDOR PART #521099 SUBURBAN, (9A-D-H-10), (STK)	1.00	184.50	184.50

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	19.49	19.49

Subtotal for Job #2: 378.99

Customer #: 93644
BOWLING, FREDDIE



W/O: 26690

Parts Total:	184.50
Labour Total:	175.00
Sublet Total:	0.00
Extras Total:	19.49
WORK ORDER TOTAL:	378.99

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 03 Mar 2026

Customer Signature : _____

Customer Work
Order



Customer #: 93644
BOWLING, FREDDIE

