

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2477760
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2SSRB8RE021549
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 053 / 053A
 ITEM # SST526BH
 DEALER RO # 26075
 CLAIM START DATE 10/23/2025
 CLAIM END DATE 12/22/2025

Labor rate: \$165.00

OWNER INFORMATION

ROBERT BURCHETT
 4809 TAZEWELL HWY
 Sneedville, TN 37869
 USA

Retail Date of Purchase 07/19/2024 WARRANTY EXPIRATION DATE 07/19/2025

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 SB-598-03-00-004408 53-1675 - SOLAR PANEL PREP WIRING - PERFORM REMEDY - Technical Service
 Bulletin/Solar Panel Controller/Install/No Tread Code

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-10-23 14:47:49 :: Complaint: Service advisory 001027 NHTSA 53-1675 Cause: Recall from Forest River to customer Correction: Unit needs solar controller added

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$82.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$82.50

Notes

.50 authorized as requested for recall

Part

Line# 1	Item #	Description				
	F100427790	SOLAR, CHARGE CONTROLLER 2024				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$34.13	Sub Freight	\$18.83
	Appr Qty	1.00	Appr Dlr Price	\$0.00	Appr Freight	\$0.00

Notes

PARTS WERE SUPPOSED TO BE SENT NO CHARGE.
 I CONTACTED PARTS MANAGER AND SHE DID A CREDIT FOR YOUR ORDER S5341033. I HAVE ATTACHED THE CREDIT INVOICE SO YOU WILL BE REFUNDED IN FULL FOR THAT ORDER

Submitted	Labor Amt	\$82.50	Approved	Labor Amt	\$82.50
	Parts & Freight	\$52.96		Parts & Freight	\$0.00
	Total	\$135.46		Total	\$82.50

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.