



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25246



WO #: 25246

Customer: 92645 - WILLIS, JANET
Address: 1845 BAYS MOUNTAIN RD
NEW MARKET, TN
37820

Home Phone: (810) 577-0053

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10925

Stock Desc: 2024 C FOREST RIVER FORESTER
3051SF

Model: 3051SF

Serial #: 1FDXE4FN2SDD01919

Chassis #: 1FDXE4FN2SDD01919

Mileage: 123

Key #: 6999

Req'n #:

License #:

Trim:

Purchase Date: 11 APR 25

Date In: 09 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 11 APR 25

Job #1 - Warranty

COMPLAINT: ROCK GUARD ON THE HOOD IS BUBBLING UP

CAUSE: ROCK GUARD IS COMING UP IN DIFFERENT SPOTS ON THE HOOD. TECH CAN NOT
SMOOTH THE EXISTING ROCK GUARD DOWN DUE THE ADHESIVE IS GONE.

CORRECTION: REMOVE ROCK GUARD AND INSTALL NEW ON THE HOOD.

LABOR 1.5

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE ROCK GUARD ON THE FRONT CAB OVER IS COMING LOOSE FROM THE UNIT.

CAUSE: ROCK GUARD HAS FAILED AND COMING OFF.

CORRECTION: REMOVE EXISTING ROCK GUARD AND REPLACE WITH NEW. REPLACE THE
DECALS THAT GET DAMAGED WHEN THE ROCK GUARD IS REMOVED.

LABOR 6.0

Subtotal for Job #2: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 10 Apr 2025

Customer #: 92645
WILLIS, JANET

