



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

Estimate: 25334 BLIZZARD, ALEX



Estimate: 25334 (Appointment Date: 25 APR 2025 - Time: 10:30am)

Customer: 71782 - BLIZZARD, ALEX

Address: P.O. BOX 2978

WISE, VA

24293

Home Phone: 276-870-7150

Work Phone:

Author: CHL

Location: IH

Invoice #: 418044

Stock #: 8602

Stock Desc: 2017 FW FOREST RIVER CEDAR

CREEK 38FBD

Model: 38FBD

Serial #: 4X4FCRP22HS217475

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 09 FEB 17

Date In: 25 APR 25

Promise Date: 30 MAY 25

Promise Time: 09:00am

Schedule Date:

Completed: 26 APR 25

Warr. Date: 09 FEB 17

**Job #1 - External**

COMPLAINT: SC TO GREEN LEAF FAMILY CAMP GROUND RUTLEDGE TN CALL BEFORE SERVICE

CORRECTION: SERVICE CALL COMPLETE

**Other Services**

Code	Description	Qty	Price	Total
SC	SERVICE CALL	0	0.00	0.00
<b>Subtotal for Job #1:</b>				<b>0.00</b>

**Job #2 - External**

COMPLAINT: CS THAT THE LIVING ROOM A/C IS NOT COOLING

CAUSE: BAD A/C 2DEG SPLIT 11AMPS AT 70DEG

**Labor**

Code	Description	Hours	Rate	Total
Z990	DIAG	0	175.00	0.00
<b>Subtotal for Job #2:</b>				<b>0.00</b>

**Job #3 - External**

COMPLAINT: CS THAT THE MAIN DOOR ENTRY LOCK IS BROKEN

CAUSE: FOUND LOCK HAD FAILED NEEDS REPLACED

CORRECTION: REPLACED LOCK

**Labor**

Code	Description	Hours	Rate	Total
Z990	REPAIR	0	175.00	0.00

**Parts**

Part #	Description	Qty	Price	Total
4727	GLOBAL LOCK BLACK	0	36.89	0.00
G-381	GLOBAL KEY 381	0	5.39	0.00
<b>Subtotal for Job #3:</b>				<b>0.00</b>

**Job #4 - External**

COMPLAINT: CS THAT THE DRYER IS NOT DRYING THE CLOTHS TAKES 3 CYCLES TO DRY CLOTHS



**Subtotal for Job #4: 0.00**

**Job #5 - External**

COMPLAINT: CS THAT THE SEAL UNDER THE BED SLIDE IS COMING APART

CAUSE: NEEDS NEW SEAL

**Subtotal for Job #5: 0.00**

**Job #6 - External**

COMPLAINT: CS THAT THE VINYL INSERT UNDER THE OVER HAND IS COMING LOOSE

CAUSE: NEEDS REPLACED TRYED TO REINSTALL BUT INSERT IS NO GOOD

**Labor**

Code	Description	Hours	Rate	Total
Z990	REPAIR	0	175.00	0.00

**Subtotal for Job #6: 0.00**

**Job #7 - External**

COMPLAINT: CS THAT THERE IS A GFI OUTLET IS INOP

CAUSE: NEEDS NEW OUTLET ,OUTLET IS NOT ALLOWING POWER TO GO THROUGH IT

**Labor**

Code	Description	Hours	Rate	Total
Z990	DIAG	0	175.00	0.00

**Subtotal for Job #7: 0.00**

**Job #ROOFINS - External**

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

- CHECK CAULKING \_\_\_\_\_
- CHECK SKYLIGHTS \_\_\_\_\_
- CHECK ROOF VENTS \_\_\_\_\_
- CHECK LUBE & ANTENNA \_\_\_\_\_
- CHECK SATELLITE \_\_\_\_\_
- CHECK RUBBER \_\_\_\_\_

CAUSE: NEEDS NEW ROOF

**Subtotal for Job #ROOFINS: 0.00**

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
 Tax Total: 0.00  
 Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 16 May 2025

