



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25708 HOLLIFIELD,
THOMAS



Estimate: 25708 (Appointment Date: 02 JUL 2025 - Time: 10:00am)

Customer: 91410 - HOLLIFIELD, THOMAS
Address: 3010 OLD PARROTTSVILLE HWY
PARROTTSVILLE, TN
37843

Home Phone: (865) 599-2356

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10897

Stock Desc: (10897) 2024 FOREST RIVER

ROCKWOOD SIGN 8263MBR

Model: 8263MBR

Serial #: 4X4TRLF23R1906044

Chassis #:

Mileage: 0

Key #: 5000

Req'n #:

License #:

Trim:

Purchase Date: 27 MAR 24

Date In: 02 JUL 25

Promise Date: 30 JUL 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 27 MAR 24

Job #1 - External

AC NOT WORKING TURNS ON BUT NOT COOLING
FRONT A/C

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

LEVELERS GO DOWN AND COME BACK UP JACKS WORK BUT BEFO THEY HIT THE GOUND IT
GETS A CODE AND THEY COME BACK UP BEFOE UNIT LEVELS

Subtotal for Job #2: 0.00

Job #3 - External

SIDE OF BED IS COMING LOOSE PANEL AT BOTTOM OF BED

Subtotal for Job #3: 0.00

Job #4 - External

HANDLE IS MISSING FROM BATHROOM FAUCET

Subtotal for Job #4: 0.00

Job #5 - External

POCKET DOOR HAS FALLEN OFF THE HINGE BATHROOM DOOR

Subtotal for Job #5: 0.00

Job #6 - External

WATER LEAK WHEN PUMP IS RUNNING CHECK AND ADVISE CAN SEE WATER LEAKING FROM
UNDER BATHROOM DOOR



Subtotal for Job #6: 0.00

Job #7 - External

CUS HAS EXT WARRANTY

Subtotal for Job #7: 0.00

Job #8 - External

CS THAT THE RUNNING LIGHTS AND BRAKE LIGHTS ARE INOP

Subtotal for Job #8: 0.00

Job #9 - External

REAR SLIDE IS STICKING OUT AT BOTTOM CHECK AND ADVISE

Subtotal for Job #9: 0.00

Job #10 - External

QUOTE ON SNAP PADS

Subtotal for Job #10: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #11 - External

CS THAT THE OUTSIDE SHOWER DOOE HANDLE HAS FALLEN OFF

Subtotal for Job #11: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Jul 2025

