



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

Estimate: 25856 KESTERSON,  
ROBERT



Estimate: 25856 (Appointment Date: 31 JUL 2025 - Time: 10:00am)

Customer: 84732 - KESTERSON, ROBERT  
Address: 330 PAINTER ROAD  
FALL BRANCH, TN  
37656

Home Phone: (910) 545-8282

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10502

Stock Desc: (10502) 2022 FOREST RIVER REAL

LITE 189

Model: 189

Serial #: 4X4TPAU18NN057603

Chassis #:

Mileage: 0

Key #: 3000

Req'n #:

License #:

Trim:

Purchase Date: 05 OCT 22

Date In: 31 JUL 25

Promise Date: 30 AUG 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 05 OCT 22

#### Job #1 - External

CS THAT THE SHOWER IS BROKEN AND ALSO LEAKS WATER CHECK AND ADVISE(OUTSIDE SHOWER)

#### Other Services

| Code | Description            | Qty | Price | Total |
|------|------------------------|-----|-------|-------|
| SSE  | SHOP SUPPLIES EXTERNAL | 1   | 0.00  | 0.00  |

**Subtotal for Job #1: 0.00**

#### Job #2 - External

CS THAT THE KITCHEN SINK IS LOOSE FROM THE BOTTOM OF THE COUNTER TOP

**Subtotal for Job #2: 0.00**

#### Job #3 - External

CS THAT THE TOILET VALVE IS LEAKING CHECK AND ADVISE

**Subtotal for Job #3: 0.00**

#### Job #4 - External

REPLACE ANODE ROD

#### Parts

| Part # | Description      | Qty | Price | Total |
|--------|------------------|-----|-------|-------|
| 60409  | 232419 ANODE ROD | 0   | 15.29 | 0.00  |

**Subtotal for Job #4: 0.00**

#### Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING \_\_\_\_\_

CHECK SKYLIGHTS \_\_\_\_\_

CHECK ROOF VENTS \_\_\_\_\_

CHECK LUBE & ANTENNA \_\_\_\_\_

CHECK SATELLITE \_\_\_\_\_

CHECK RUBBER \_\_\_\_\_



**Subtotal for Job #ROOFINS: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
Tax Total: 0.00  
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 07 Aug 2025

