



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26048 LANE, CURTIS



Estimate: 26048 (Appointment Date: 09 SEP 2025 - Time: 10:00am)

Customer: 93208 - LANE, CURTIS
Address:
, TN

Home Phone: (859) 907-7476
Work Phone:
Author: CHL
Location: IH
Invoice #:

Stock #:
Stock Desc: 2004 A WINNEBAGO JORNEY
Model:
Serial #: 4UZAABV34CN01909
Chassis #:
Mileage: 52793
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 09 SEP 25
Promise Date: 30 SEP 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CS THAT THE FRESH WATER TANK DRAIN VALVE IS LEAKING AND WON'T HOLD WATER IN

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - External

CS THAT THE BIG SLIDE IS HITTING THE FLOOR THEY WOULD LIKE TO SEE IF WE CAN ADJUST IT

Subtotal for Job #2: 0.00

Job #3 - External

CS THAT THE BIG AWNING FABRIC IS IN NEED OF REPLACING CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - External

CS THAT THE LARGE SLIDE TOPPER FABRIC IS IN NEED OF REPLACING CHECK AND ADVISE

Subtotal for Job #4: 0.00

Job #5 - External

CS THAT THE SLIDE TOPPER/AWNING OVER THE DOOR NEEDS NEW FABRIC CHECK AND ADVISE

Subtotal for Job #5: 0.00

Job #6 - External

CUSTOMER WOULD LIKE A QUOTE ON ADDING A SUN SHADE TO THE MAIN AWNING



Subtotal for Job #6: 0.00

Job #7 - External

CHECK LUG NUTS TO SEE IF THEY ARE AT THE PROPER TORQUE

Subtotal for Job #7: 0.00

Job #8 - External

CHECK SLIDE SEALS

Subtotal for Job #8: 0.00

Job #9 - External

LP DROP DOWN TEST

Subtotal for Job #9: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 12 Sep 2025

