



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26086 COLE, DANIEL



Estimate: 26086 (Appointment Date: 18 SEP 2025 - Time: 11:00am)

Customer: 89316 - COLE, DANIEL
Address: 116 ARLINGTON CIRCLE
KINGSPORT, TN
37663

Home Phone: 423-943-0411

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #:
Stock Desc: 2008 C FOREST RIVER LEXINGTON
Model:
Serial #: 1FDXE45S07DB20042
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 18 SEP 25
Promise Date: 30 SEP 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date:

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #ROOFINS: 0.00

Job #1 - External

CHECK A/C FOR LEAKS INTO THE COACH CHECK WHERE STAINS IN THE CEILING ARE COMING FROM

Subtotal for Job #1: 0.00

Job #2 - External

CS THAT THE HEAD LINER IS HANGING DOWN OVER DRIVERS SEAT CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - External

CS THAT THE OUT SIDE SHOWER KEEPS CRACKING HOSES WHEN PUT INTO STORGE LOCATION

Subtotal for Job #3: 0.00

Job #4 - External

CS THAT THE SEAL UNDER THE BEDROOM SILDE KEEPS COMING LOOSE CHECK AND ADVISE



Subtotal for Job #4: 0.00

Job #5 - External

CUSTOMER ASKED IF WE COULD ADD USB PLUGS AROUND THE DINNING ROOM TABLE

Parts

Part #	Description	Qty	Price	Total
89-8304	TWIST ON VALVE 3"	0	39.99	0.00

Subtotal for Job #5: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	0.00
Estimate Total:	0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 24 Sep 2025

