



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 26647 WILLIAMS,
 RUSSELL



Estimate: 26647 (Appointment Date: 20 JAN 2026 - Time: 09:30am)

Customer: 93601 - WILLIAMS, RUSSELL
 Address:

Home Phone: 908-839-7454

Work Phone:
 Author: S.DAVIS

Location: IH
 Invoice #:

Stock #:
 Stock Desc: 2023 FOREST RIVER ROGUE 351G2
 Model: 351G2
 Serial #: 4X4FVGL22P5402661
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim: 351G2

Purchase Date:
 Date In: 20 JAN 26
 Promise Date: 28 FEB 26
 Promise Time: 09:00am
 Schedule Date:
 Completed:
 Warr. Date:

Job #1 - External

EXT WARRANTY WITH RV AMERICARE
 CUST HAS A TRIP FIRST OF FEB

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

TOILET IS LEAKING

Subtotal for Job #2: 0.00

Job #3 - External

THE BED MOTOR/GEAR IS SLIPPING AND GOES DOWN IN THE MIDDLE OF THE NIGHT

Subtotal for Job #3: 0.00

Job #4 - External

2 WINDOWS ON PASSENGER SIDE (BEDROOM AND LIVING ROOM) THE LOCKS DO NOT HOLD
 WINDOWS CLOSED. THESE WINDOWS ARE COMING OPEN DURING TRAVEL,

Subtotal for Job #4: 0.00

Job #5 - External

SPEAKER IN GARAGE AREA THE BLUE LIGHT IS OUT

Subtotal for Job #5: 0.00

Job #6 - External

FURRION OUTDOOR CAMERAS WILL NOT WORK AND HAS NOT SINCE THE DAY OF PURCHASE
 THERE IS 4 TOTAL GARAGE, REAR AND 2 SIDE CAMERAS



Subtotal for Job #6: 0.00

Job #7 - External

RIGHT REAR TAIL LIGHT IS HALF WORKING

Subtotal for Job #7: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 Jan 2026

Customer Estimate

