

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106  
 BASDEN RV CENTER INC  
 DBA AMERICAN RV CENTER  
 600 E BASELINE ROAD  
 EVANSVILLE, IN 47725  
 USA

CLAIM STATUS Authorized  
 CLAIM 2645074  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZTCFLS03TP432862  
 CHASSIS VIN 1FDWE3FN7SDD30130  
 MILEAGE 4150  
 SITE/WAREHOUSE 210 / 210  
 ITEM # FLC27QBF35  
 DEALER RO # 79422  
 CLAIM START DATE 04/16/2026  
 CLAIM END DATE 01/01/1900

Labor rate: \$195.00

**OWNER INFORMATION**

CHUBBY CHOW FACTORY LLC FACTORY LLC  
 PO BOX 3641  
 Evansville, IN 47715  
 USA

Retail Date of Purchase 05/07/2025      WARRANTY EXPIRATION DATE 05/07/2026

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 20-66-01-17-000668      Entry Door Lock - Exterior/Entry Doors/Replace/Latch  
**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2026-04-16 16:00:40 :: ENT DOOR LOCK DEADBOLT IS JAMMED UP. KEY WILL NOT GO IN AND DOOR IS RANDOMLY STAYING LOCKED WHERE YOU CANT UNLOCK FROM INSIDE OR OUTSIDE Entry door Brought unit in. Tried to open entry door and it would not open. Tried getting key into lock. After several attempts key turned to unlock door but would not unlock. Tried on deadbolt and lock itself would not move. Tried again on door lock and it eventually opened. Door handle apart and saw components of door lock are not working. Parts request submitted for entry door lock. Received new entry door lock and handle. Removed old lock from unit. Placed new one in and checked to make sure door opens and closes properly when unlocked. Door opens and closes properly  
**Model#**      **Dir Sub Hrs**      0.30      **Sub Labor Amt** \$58.50  
**Serial#**      **Appr Hrs**      0.30      **Appr Labor Amt** \$58.50  
**Notes**

**Labor**

Line# 2      **Operation Code**      **Operational Description**  
 30-102-12-00-002691      Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2026-04-16 16:01:17 :: TOILET PAPER HOLDER IS NOT INSTALLED INTO STUD AND PULLED OUT OF WALL PANEL Toilet paper holder Went inside unit and saw toilet paper holder was not in stud to hold in place. Found stud and lined up holder to even out. Shot screws in wall to secure. Place wood putty in old holes.  
**Model#**      **Dir Sub Hrs**      0.20      **Sub Labor Amt** \$39.00  
**Serial#**      **Appr Hrs**      0.20      **Appr Labor Amt** \$39.00  
**Notes**

<b>Submitted</b>	Labor Amt	\$97.50	<b>Approved</b>	Labor Amt	\$97.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	<b>Total</b>	<b>\$97.50</b>		<b>Total</b>	<b>\$97.50</b>

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.