



# Warranty Claim Detail

R.O. Number **73042**  
 Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	26V 108
Description	NEWMAR - SECURE BSCA BTCA HOOD BRACKETS
Occurrences	1
Requested Hours	.30
Authorized Hours	.30
Fault Code	42-Recall
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

GENERAL INFORMATION	
Status	Paid
Date In	03/16/2026
Submit Date	04/14/2026
Authorization	No 04/14/2026
Work Complete	Yes 04/14/2026
Payment	Yes 04/23/2026

CUSTOMER COMPLAINT
COMMENT ENTERED ON 04/14/2026 AT 09:17 AM BY DEALER Recall for hood stop

AUTHORIZATION NOTES

DEALER CORRECTION
COMMENT ENTERED ON 04/14/2026 AT 09:17 AM BY DEALER Drill and add a bolt to secure one on left and right side

TOTALS	Requested	Authorized
Labor	55.50	55.50
Sublet	.00	.00
Parts	2.92	2.92
Freight	.00	.00
Adjustments	.00	.00
<b>TOTAL</b>	<b>59.29</b>	<b>59.29</b>
TOTAL PAID		<b>59.29</b>

