



# KEYSTONE

## Pre-Authorization

Pre-  
Authorization  
number

PREAUTH102112  
(PA03993317)

Reference no.40438

Status

Approved

Servicing Dealer 16105 Name Link Ford & RV Minong LLC Address 1025 Hokah St Minong, WI 54859 VIN 4YDFAVT25TE760169 Retail sold on 4/24/2026

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
2105114B	Slide Out Box, Main Wall Opening Mldg, Bulb Seal	0	1	1		1	1	<p><b>Complaint:</b> Dealer states that the forward bedroom slide seal is detached.</p> <p><b>Cause:</b> Metal sleeve for the seal was not pinched off at the top sufficiently.</p> <p><b>Correction:</b> Bent top of sleeve out, reinserted seal, recrimped sleeve at the top and bottom. Bottom was difficult to reach.</p>
3201814A	Decorative Wood Trim - Repair - per piece	0	0.5	0.1		1	0.1	<p><b>Complaint:</b> Dealer states that there is loose trim above the couch.</p> <p><b>Cause:</b> There was not an adequate amount of fasteners.</p> <p><b>Correction:</b> Refastened the loose trim and covered the nail holes with putty.</p>
3201816A	Decorative Wood Trim - Repair - per piece	0	0.5	0.1		1	0.1	<p><b>Complaint:</b> Dealer states there is loose trim up the steps by the door.</p> <p><b>Cause:</b> Loose trim</p> <p><b>Correction:</b> Refastened trim.</p>
2400206B	Die Cut - Over 3' long - Replace	0	1.5	1		1	1	<p><b>Complaint:</b> Dealer stated exterior decal peeling by back.</p> <p><b>Cause:</b> Faulty decal.</p> <p><b>Correction:</b> Remove and replace decals.</p>
Pre-Authorization number: PREAUTH102112				2.2				

For paper claims only use one pre-authorization number per warranty claim form.  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.