



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79508
Promised Date:
26 APR 26

CUSTOMER WORK ORDER

WO #: 79508

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0424 CHECK WORK

Stock #: 11741

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 23MS

Chassis #: 4X4TCKY28TK099840

Serial #: 4X4TCKY28TK099840

Mileage: 0

Licence:

Invoice #:

Date In: 08 APR 26

Promised: 30 APR 26

Date Sched:

Completed: 24 APR 26

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Inspected roof and found 2 tiny voids in front of unit which i filled with Dicor. Hooked up mu person Battery. Checked Coupling, Safety Chains, Lights, breakaway switch and brakes. Checked tonguejack (lights out on tonguejack) and light doesn't work. Checked Cap Seals. Rolled underbelly and inspected and closed valves. Filled Fresh water tank to 2/3. Checked cargo rack in rear. Checked doors and compartment seals. Pulled zIP cover and Tanks to Fill. Hooked up units Shore Power Cord. Tested Stabilizer Jacks. Going to turn valve on water pumpmto Dewinterize unit and i have to remove cabinet door and screws are thru the Front Face of Cabinet and not thru panel like normal. After removing door and face screws, it turns out they serve no purpose. After lifting mattress off of bed frame i see where they cut a access hole under bed on frame. Dewinterized unit. Filled Black and Grey tank to 2/3. Attempted to checked Recepticals...12v USB ports work properly but the 120v recepticals dont work, attempted to flip GFCI switch but cant reset Receptical. Attempting to do LP DropTest but the Furnace is not firing and Water Heater is reading EU code. I used my bleeder in my Manometer at Quick Connect outside and gas is going thru lines?! When running the Water Heater and Slideroom, all 12v lights in Ceiling are flickering. Found out that my ShorePower cord had been pulled from plug and not locked in which resolved my Electrical issues. Checked all my 12v USB ports and 120v recepticals. Preformed LP DropTest. Tested Microwave, Fridges (plugged in previous day) and removed packing off of them. Tested Bluetooth Radio. Tested AC. Tested Stovetop and outside grill. Tested Hood Light and vent. Checked all drawers, cabinets, doors, blinds and windows. Checked mini inverter in bedroom. Checked hideaway pantry. Checked electric fireplace. Went to test Outside Grille but the Quick connect Gas hose cant connect to Grill due to position of quick connect. After looking the grill over i realized that if you lifted the front grille tray and pull outward that it extended and there was a cutout in the direction of the quick connect. Tested Grille. Retrieved Test TV and checked Antenna Reception. While closing up unit and closing outside compartment doors the Doorside rear compartment door rubs frame on the back bottom corner. 28in x 17in inside measurement.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 79508
Promised Date: 30 APR 26



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: TOUNGE JACK WILL NOT LIGHT UP

CAUSE: Replace Tonguejack

CORRECTION: Replaced Tonguejack

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: LIGHT FLICKERING WHEN USING THE WATER HEATER ON SLIDE

CAUSE: Loose shore power cord

CORRECTION: Shore power cord wasnt securely plugged in and battery was low

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: FURNACE AND WATER HEATER NOT FIRING AND GIVING A CODE

CAUSE: Loose Shore power cord

CORRECTION: Found my shore power cord wasnt fully plugged in

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: GFCI WILL NOT RESET

CAUSE: ShorePower Cord not locked in.

CORRECTION: Pulled GFCI plug from bathroom and found no power there. Checked my ShorePower coming in and plug was not lock in all the way. Reassembled the GFCI outlet in bathroom.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C



Subtotal for Job #4:

0.00

Job #5 - Warranty

COMPLAINT: THE OUTSIDE COMPARTMENT DOOR IS RUBBING THE FRAME WHEN OPENING AND CLOSING.

CAUSE: Door bad from factory

CORRECTION: Took pics and measurements for compartment door which rubs the frame when closing
Removed old door and installed new door. Applied caulking seam

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
5952	15.75 X 27.75 COMP DOOR - BLACK	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	N/C	N/C

Subtotal for Job #5:

0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Apr 2026

W/O: 79508
Promised Date: 30 APR 26



Customer #: 1000
BASDEN'S AMERICAN RV,

